	Ty pe	١	Hits	Search Text	DBs	Time Stamp	en	Dα	Er ro rs
1	BR S	L1	284	(malfunction or		2005/ 10/13 19:12		·	
2	IS &R	L2	8937	(455/9,13.3,26.1,63. 4,67.11,68,82,115.1, 115.4,121,123,129,19 3.1,226.1,423,562.1, 550.1,575.7).CCLS.	US-PGPUB; USPAT;	10/13			
3	IS &R	L4	606	11.15.	US-PGPUB; USPAT; EPO; JPO	- • ,			
4	IS &R	L3	2031	1.094.0/D1.(\ L\S	US-PGPUB; USPAT; EPO; JPO	/			
5	BR S	L5	1145 2	2 or 3 or 4	US-PGPUB; USPAT; EPO; JPO	10/13			
6	BR S	L6	20	5 and 1	US-PGPUB; USPAT; EPO; JPO	10/13			
7	BR S	Ь7	618	second with switch\$4	US-PGPUB; USPAT; EPO; JPO	10/13			
8	BR S	L8	491		USPAT; EPO; JPO	10/13 19:10			
9	BR S	Ь9	501	5 and antenna with second with switch\$4 with first	-	10/13			

A								Er	
								ro	
							Co	r	Er
	Ту		Hits	Search Text	DBs	Time	mm	De	i I
	рe	#				Stamp	en	fi	rs
							ts	ni	1 1
								ti on	
	-			9 and (monitor\$4 or	TIC DONIE.	2005/		011	
10	BR	L1		i	USPAT;	•			
	S	0			EPO; JPO	1			
-				10 and (malfunction	·				
11	BR	L1	3		USPAT;	•			
	S	1		antenna	EPO; JPO	19:12			
	BR S	T.1		(monitor\$4.ti. or	US-PGPUB;	2005/			
12		2	1 444		USPAT;	10/13			
					EPO; JPO	19:14			
	BR S	L1 3	290	(monitor\$4.ti. or	US-PGPUB; USPAT; EPO; JPO	2005/			
13				diagnosss) with		-			
				antenna and antenna.ti.					
				ancema.cr.	US-PGPUB;	2005/			
14	BR S	L1	52	5 and 13	USPAT;				
		4			EPO; JPO				
			ł.	switch\$4 with second with antenna.bsum.					
					US-PGPUB;	2005/			
15	BR		227		USPAT;	l .			
	S	5		problem or error or	· ·				
				fail\$4 or	·				
				fault).bsum.					
		тэ		monitoring.ti. and antenna.ti.	US-PGPUB;	2005/			
16	BK S	(L) Т	11/11		USPAT;	1			
	٥	٥			EPO; JPO	19:17			
	BR	T,1	1164 1	monitor\$4.ti. and antenna.ti	US-PGPUB;	1			
11/		7			USPAT;				
L					EPO; JPO	19:17			

Å.	Ty pe	ŀ	Hits	Search Text	DBs	Time Stamp	en	De fi	ro
18	BR S	L1 8	45	1 and (malfunction\$4 or problem or error or fail\$4 or fault).bsum. with antenna	US-PGPUB; USPAT;	10/13			
19	BR S	L1 9	94	1	US-PGPUB; USPAT; EPO; JPO	10/13			
20	BR S	L2 0	8	5 and 19	US-PGPUB; USPAT; EPO; JPO	10/13			
21	BR S	L2 1	11	is and ancenna near)	US-PGPUB; USPAT; EPO; JPO	10/13			
22	BR S	L2 2	266	(Connect\$4 or attach\$4) with nower	US-PGPUB; USPAT; EPO; JPO	10/13			
23	BR S	L2 3	12.12.4	o and switch\$4 with	US-PGPUB; USPAT; EPO; JPO	10/13			
24	BR S	L2 4	309	,	US-PGPUB; USPAT; EPO; JPO	10/13			
25	BR S	L2 6	241	amplifier or preamp	US-PGPUB; USPAT; EPO; JPO	10/13			

<i>1</i> **	Ty		Hits	Search Text	DBs	Time Stamp	mm	na.	Er ro rs
26	BR S	L2 7	1840	antenna.ti. and switch\$4.ti.	US-PGPUB; USPAT; EPO; JPO	10/13			
27	BR S	L2 8	112	27 and 5	US-PGPUB; USPAT; EPO; JPO	10/13			
28	BR S	L2 9	276		US-PGPUB; USPAT; EPO; JPO	10/13			
29	BR S	L3 0	94	display with	US-PGPUB; USPAT; EPO; JPO	10/13			
30	BR S	L3 1	1	5 and inform\$4 with display with		2005/ 10/13			
31	BR S	L3 2	8	display with (malfunction or replac\$6).bsum. with antenna	US-PGPUB; USPAT; EPO; JPO	2005/ 10/13 19:25			